Coroners Inquest

917 Dundas Street W, Whitby 2016 OMFPOA Symposium



Fire Chief Dave Speed CFPO Nicholas Webb

Outline

- 1. Building Description and Background
- 2. Fire
- 3. Inquest
- 4. Challenges
- 5. Lessons Learned
- 6. Moving Forward

1) Building Description and Background

- Inspected in October 2008 three dwelling units
- 9.5 not zoned.
- Installed smoke alarm, and issued Report 2.1.2.2. return to single family dwelling.



Building Description and Background

- No work was done. Charges laid, trial, guilty verdict.
- Owner turned into 2 dwelling units.
- Issued Report 9.8
- February 2010 Compliance
- Building contained two approved, registered dwelling units – second floor unit, and main floor unit
- No interior connection to basement used for storage
- Exit to common breezeway
- Laundry located in basement, along with storage

2) Fire

- Initial call was received on 29 April, 2012, 00:25:43.
- Call was made from the 2nd floor tenant and two friends who were visiting in the apartment.
- The cell phone remained connected to 911 throughout the entire call.
- No one home in the main floor/basement unit.
- The fire started in 2nd floor unit accidental cooking fire that quickly blocked the only egress out of the 2nd floor unit.
- All occupants of the 2nd floor unit perished in the fire.

3) Inquest

An inquest was called by the Coroner to determine what could be learned from this event to help prevent it from happening again.

- 2 types of inquest Mandatory / Discretionary
- Mandatory: Deaths at construction sites, mines, pits or quarries, in custody, child death, psychiatric facility
- Discretionary: The coroner may also determine whether or not it is desirable for the public good.

Inquest

Parties with Standing:

OFMEM Family

OPFFA Safety League

East Gwillimbury DRPS

City of Oshawa Town of Whitby

4) Challenges

Emotional Intellectual

Media

Family

Fire Personnel

Politicians

OFC Application

Controversial: Number of exits required? 2 or 1?

One means of escape

- 9.8.3.2. (1) Each residential unit shall be served by at least one means of escape consisting of a door that
 - (a) serves only that residential unit,
 - (b) opens directly to the exterior from that residential unit, and
 - (c) has direct access to ground level.
- 9.8.3.3. (1) Each residential unit shall have direct access to at least one means of escape that may be shared if
 - (a) the means of escape is separated from the remainder of the building by a fire separation having a fire-resistance rating not less than 30 min,
 - (b) the flame-spread rating of interior wall and ceiling finishes within the means of escape does not exceed 150, and
 - (c) the means of escape does not involve entering another residential unit or other occupancy and leads directly to the exterior with direct access to ground level.
- (2) Where a means of escape provided by Sentence (1) serves a residential unit situated entirely on the third storey, the detached house, semi-detached house or row house shall be equipped with interconnected smoke alarms conforming to Article 9.8.4.1.

OFC Application



Stairs leading from the 2nd floor unit



Upstairs dropped ceiling and paneling



Breezeway paneling

5) Lessons Learned - Be Prepared

- ✓ Hire law firm
- ✓ Cannot have enough preparation meetings
- ✓ Constant communication
- ✓ Read everything multiple times (900 page brief)
- ✓ Full-time job
- ✓ Hold multiple meetings with all witnesses, and those impacted
- ✓ Provide EAP/CIS/Counselling services
- ✓ Cannot communicate too much

- ✓ Testimony always remain professional
- ✓ Don't state something unless you're confident it is correct credibility.

Differences between Coroner's Inquest and other Courts:

- Jury can ask questions
- Rules of evidence are less strict
- Cross examined by multiple parties/lawyers
- No Judge/JP Coroner.

5) Lessons Learned - Unprepared?

1) Media:

In courtroom

Some reports were not accurate

Discussions because of media – consultant, Council, CAO WFES Family, lawyers,

2) The OFMEM:

Cross-examined very aggressively by the OFMEM lawyer

- 3) Family emotional presence
- 4) Truth:

this is supposed to be about providing the facts so that the Jury has the information to make recommendations. This may be true, but it is also about some parties defending their actions by trying to point the finger at others.

6) Changes

As a direct result of the Coroners Inquest recommendations, WFES has made the following changes to the way we deal with accessory apartments:

- Units do not need to be utilized, as long as all 5 elements of a dwelling unit are present
- Notes, photo's, sketches to be done on site
- Inspection Orders under 21 (1) (f) or (g) to be issued
- Re-inspection time frame moved up from 90 to 30 days
- Building department to receive a copy of Inspection Order, and FPO to receive a copy of the building permit plans for review

6) Changes

- Upon re inspection, Inspection Order must be complied with, or 1 of the 5 elements must be permanently removed
- Notes and photos must be taken showing the completed work
- If the unit contains a drop ceiling or wood paneling, these items must be completely removed to verify the existence of drywall
- WFES has revised the SOG to reflect these new changes
- An video is being created with the cooperation of the family to be used as an educational tool for teenagers (hard to reach audience)

